**To:** Bill Simon[wsimon@frontier.net]; Peter Butler[butlerpeter2@gmail.com]; Steve Fearn[fearneng@rmi.net]; Allen Sorrenson - DNR[allen.sorenson@state.co.us]; Way,

Steven[way.steven@epa.gov]

Cc: Steven Renner - DNR[steven.renner@state.co.us]

**From:** Brown - DNR, Kirstin **Sent:** Mon 4/14/2014 9:16:55 PM

Subject: Gold King and Sunnyside Workings and Drill Holes Map

GoldKing Sunnyside DrillHoles.pdf

Here is a map showing the Gold King workings and Sunnyside Workings, including drill holes. The drill information has no dip azimuth information. So, I measured everything in plan view along a horizontal plane. So essentially this is worst case scenario.

The actual distance between Gold King 7 and the drill hole are almost surely farther.

Let me know if you have any more questions.

Distance = 370 feet to Sunnyside drill hole from Gold King 7

--

Kirstin Brown
Colorado Division of Reclamation, Mining and Safety
691 C.R. 233, Suite A-2
Durango, CO 81301
(970) 903-7889
kirstin.brown@state.co.us